



OFFICE RS 60

Mebel należy montować na miękkim podłożu

Mebel należy konserwować typowymi środkami do konserwacji mebli







Furniture should be assembled on the soft surface

Piece of furniture should be preserved by the typical furniture care substances




OKUCIE: / FITTINGS:

B1 8x35 x24	M1 12x15 x12	T1 x24	S5 3,5x16mm x1	S8 3 x 20 mm x12
B3 6x30 x12	M3 10x15 x12	G2 1,4x25mm x65	T19 x1	R25 300mm x3
K5 x4	C2 x16	F36 x4	T20 x1	
S6 4 x 16 mm x8	G7 x1	K1 7,0x50 x6	W1 x8	S7 6,3x13mm x12




1




1

2



6 (x3)



B1 8x35 x24

M1 12x15 x12

F36 x4




R25






T1 x12

300mm x3
















S7 6,3x13mm x12

W1 x8










2**3**


C2 x4




4**5**

K5		x4	S6		4 x 16 mm	x8	S5		3,5x16mm	x1	T19		x1	T20		2 x 16 mm	x1	G2		1,4x25mm	x36
-----------	--	----	-----------	--	-----------	----	-----------	--	----------	----	------------	--	----	------------	--	-----------	----	-----------	--	----------	-----

6**7**

B3	6x30	x12
C2		x12
M3	10x15	x12
K1	7,0x50	x6
T1		x12
G7		x1



8**9**