











 +8x30mm A	 +6x42mm B2	 +15/12mm C	 +12/10mm C5	 L=20mm D2	 E	 +15x5mm F4	 +35/16mm HG2	 27/310mm I4	 +5/16mm J3	 J12
44	6	16	6	22	4	5	4	3	8	2
 L	 L2	 L9	 +6,3x13mm M2	 +10x50mm O7	 +4.0x16mm P1	 +3.5x13mm P5	 +3.0x20mm P7	 L=32mm S	 M4x9mm T3	 U1
15	8	1	12	1	2	9	17	5	1	6

ISM-TNO-004



	Ersatzteil Nummer	Dimension
	TNO.106	727x399x16
	TNO.107	727x399x16
	TNO.503	631x383x16
	TNO.504	631x383x16
	TNO.303 x2	370x350x16
	TNO.607 x3	650x384x2,5
	WST.0269 x3	337x140x12

	Ersatzteil Nummer	Dimension
	TNO.204	1179x400x16
	TNO.404	1145x384x16
	TNO.904	1145x80x16
	TNO.608 x3	348x327x2,5
	WST.0156 x3	330x140x12
	WST.0157 x3	330x140x12
	TNO.703 x3	205x367x18
	TNO.704 x2	623x367x18




TMR.204



TMR.404



TNO.303








TNO.608


1

+12/10mm  C5 6	+8x30mm  A 24
---	--

x3





2





x3

+6x42mm  B2 6





3









x3

L=20mm  D2 6


4






x3
















5

















x3







$\varnothing 8 \times 30 \text{ mm}$  A	$\varnothing 15/12 \text{ mm}$  C	$L=20 \text{ mm}$  D2	$\varnothing 15 \times 5 \text{ mm}$  F4	$27/310 \text{ mm}$  I4	$\varnothing 6,3 \times 13 \text{ mm}$  M2
12	12	4	4	3	12




 $\varnothing 8 \times 30 \text{mm}$	 $\varnothing 15/12 \text{mm}$	 L=20mm		 $\varnothing 4.0 \times 16 \text{mm}$	 $\varnothing 15 \times 5 \text{mm}$
A	C	D2	T3	P1	F4
8	4	12	1	1	1







8








9












10












11




3.0x20mm		
		
P7	L2	L
17	8	9





$\varnothing 10 \times 50 \text{ mm}$ 		$\varnothing 3.5 \times 13 \text{ mm}$ 
O7	L9	P5
1	1	1




14








		
J12	J3	E
2	8	4



15





L=32mm	M4x9mm
	
S	U1
3	6



16

 HG2 4	 P5 8
--	---



17

 L=32mm S 2

