











K30  20	T1  28	M1  28	Z15  4	PZ  4	X  28	Z9  4
STB  16	W4x16  44	NB  5	ODB  4	PP  8	PZ9  4	





T1	ODB
20	4
	W4x16
	8








T1	PZ	M1	K30
2	2	4	4






T1  6	PZ  2	M1  12	K30  12
PP  4			









W4x16  16	Z15  4	Z9  4
--	--	---



M1  8





W4x16



20




NB

5




STB


16





STB



A=B



W4x16



90°

