














Typ 031





1








3




4




5





6






7







8








	$\phi 4.0 \times 30 \text{ mm}$	L=128mm
J5	R2	S11
2	2	1






9



	$\phi 3.5 \times 13 \text{ mm}$	$\phi 10 \times 50 \text{ mm}$
L9	P5	O7
1	1	1







10




15/12mm	8x30mm	L=20mm		4.0x30mm
C	A	D2	K	P8
12	8	12	2	4


11




12






13





14





15






	
J12	E
4	12



16



		
J5	R2	S11
2	2	1



 #5.0x60mm P12	 #10x50mm O7	 K16
4	4	2

